



Also available as **CAPBs**®

**FT 30** 





- High accuracy
- Four-digit LC display for temperature, dew point and relative humidity
- Min./max. and Hold function
- Magnet in protective housing for hands-free operation
- Robust protective housing against dirt, impact and shock
- Various probe versions

Application For temperature and relative humidity measurements as well as fast checks of climatic conditions in rooms.

The different types of probes are permanently connected to the measuring instrument.

FT30: With probe at housing of measuring instrument

FT40: With probe at flexible spiral cable

FT 50: With probe at 30 cm probe

# Technical specifications

#### Measuring range temperature

-40/+80 °C

#### Measuring range humidity

0/100 % rH

## Measuring range dew point (calculated)

-40/+120 °C

## Operating temperature range

Ambient: 0/40 °C

## Hours of operation

100 hours

## Weight (with battery)

220 q/290 q

(depending on version)

#### **Dimensions**

W x H x D 66 x 143 x 37 mm

#### Display

LCD, transflective W x H: 46 x 48 mm

### Indication of measured values

°C or °F

# Supply voltage

2 x 1.5 V AA batteries

# Scope of delivery

Measuring instrument with batteries







| DG: H, PG: 4  | Part no. | Price € |
|---|----------|---------|
| Humidity/air temperature measuring instrument FT 30 | 570052   |         |
| Humidity/air temperature measuring instrument FT 40 | 570053   |         |
| Humidity/air temperature measuring instrument FT 50 | 570054   |         |

